

## Brown & Sharpe Gauge Thicknesses

Use this handy guide to quickly, easily and accurately convert gauge sizes into inches or millimeters—or vice versa.

Gauge	Millimeters	Inches
0	8.26	0.325
2	6.54	0.257
4	5.19	0.204
6	4.12	0.162
8	3.26	0.128
10	2.59	0.102
12	2.05	0.081
13	1.83	0.072
14	1.63	0.064
15	1.45	0.057
16	1.29	0.051
18	1.02	0.04
19	0.912	0.036
20	0.812	0.032
21	0.723	0.028
22	0.644	0.025
23	0.573	0.023
24	0.511	0.02
25	0.455	0.018
26	0.405	0.016
27	0.36	0.014
28	0.321	0.013
29	0.286	0.011
30	0.255	0.01
32	0.2019	0.008
34	0.16	0.0063